

ADDENDUM NO. 4

DATE: August 31, 2010
TO: PROSPECTIVE BIDDERS
PROJECT: HYNES CONVENTION CENTER EXTERIOR ROOF AND EXTERIOR ENVELOPE REPAIRS

This Addendum forms part of and modifies Bidding and Contract Documents dated August 18, 2010. Acknowledge receipt of this Addendum in writing in the space provided on BID FORMS.

Where any original item called for in the Project Manual or indicated on the Drawings is supplemented hereby, the supplemental requirements shall be considered as added thereto.

Where any original item is amended, voided, or superseded hereby, the other provisions of such items not specifically amended, voided, or superseded shall remain in effect.

The following changes shall be made to the contract documents:

ADDENDUM #004

Addendum to Exterior Envelope Repairs, Hynes Convention Center, MCCA, Boston, Massachusetts. The following document is revised as indicated:

Section 08920 – Aluminum Curtain Wall Repairs

Para. 2.02 – Glazing Materials:

Modify to read as follows:

- A.1 Exterior Gasket: Continuous extruded silicone or silicone compatible EPDM gasket with vulcanized corners, 40-60 Shore A Durometer, contractor to select and verify appropriate sizes to maintain weathertight seal.